



The following guidelines are designed to help you care for your trade show display product(s). Following these instructions will greatly increase the life of your product.

IMPORTANT: Always handle hardware products with clean hands in a clean area. Gloves and a dropcloth are a good idea if you have access to them.

Storage

- Check for dirt or stains before storing your product. If necessary, follow the instructions for stain treatment below.
- Storing the equipment in their original transport cases will help ensure proper protection of the hardware and parts.
- Store in a dry and temperature regulated area (40-80F). Extreme heat or cold could potentially damage the materials.

Cleaning

- Dust and dirt can be easily removed with a soft damp cloth.
- Using only non-scratching materials and avoid steel wool and ammonia-based window cleaner.
- Pitting and marks can be removed by polishing aluminum with car wax to shine and protect the product.

Stains

- Clean any discoloration with a solution of 1/2 cup vinegar in one quart of water; rubbing saturated cloth in a circular motion over stain.
- A soft bristled brush or non-scratching cleaning pad can help agitate the stain.
- Using a clean dry cloth to wipe the surface dry prior to storage.